

FIG-2A




FIG-3A




FIG-4




FIG-11A




FIG- 11B




FIG-11C




FIG-19





FIG-23





FIG-25





FIG-27





FIG-29






FIG-29A



SHEET 11 OF 12 DOCKET 2574
INVENTOR: Morgan et al.
TITLE: Nozzle Assembly Removal
Arrangement
S.N. 09/955,713
Replacement Dwg. Fig. 34A

BRETT A. SCHENCK
HOOVER COMPANY
10 EAST MAPLE STREET
NORTH CANTON OH 44720
PHONE: (330) 499-9200 EXT. 2515




FIG-34A




FIG-38